

CLUB REDFERN

ABN: 86 001 864 437

1st July 2022

Dear Members and Guests,

After undertaking a risk assessment on the clubs public areas, two areas of concern have been identified and require further urgent assessment and remedial action applied to eliminate risk.

The first of these is the ceiling at the front of the club. This ceiling has begun to tear resulting in the exposure of electrical wiring. This exposed wiring has been identified as a major risk to everyone entering the club, exiting the club and staff working in this area.

The second area of concern is a leak in the male toilets which is constantly pooling large amounts of water on the floor of the said area. The leak is presenting a major slip and fall risk, which needs urgent remedial attention.

Given that the front door entry - exit area and men's restrooms are out of order as a result of the above mentioned maintenance issues, the clubs bar and gaming areas will be closed on Monday 4th July for a number of days to eliminate risk to patrons. In house dining will also be unavailable yet Billy's restaurant will remain open for take away meals.

Thanks for understanding.

Regards



Anthony MacAlpine
General Manager.